

## **Type**

Uula Graphite Paint is a traditional metal roof paint made of boiled linseed oil and graphite powder.

## **Intended use**

Unpainted or previously painted metal roofs and eave gutters.

## **Technical qualities**

Gloss grade: Semi-matt.

Contains: VOC max. 300 g/L

EU VOC -limit value: (cat A/d) 300g/L (2010).

## **Colours**

Graphite Grey.

## **Application & conditions**

Ordinary or levelling paint brush.

The surface to be painted must be dry, the relative air humidity below 80% and the temperature at least +10°C.

## **Drying time**

At 20°C and 80 % relative humidity: tack-free in approximately 24 hours, depending on the circumstances. A new coat can be applied after approx. 5 days.

## **Coverage**

6–8 m<sup>2</sup>/L

## **Thinner**

Uula Oil Paint Thinner 1166.

## **Container sizes**

0.9 L, 2.7 L and 9 L

## **Cleaning of equipment**

Clean the equipment with Uula Universal Thinner or petroleum spirit and rinse with soap and water.

## **Storage & disposal**

Keep in a cool and dry place. Keep out of the reach of children Does not freeze.

Dry and empty containers can be taken to a refuse dump.

Liquid waste must be taken to a municipal hazardous waste collection point.

## **Fire classification**

Non-flammable.

Caution: Linseed oil on cleaning rags etc. may catch fire by itself. Oily rags and cloths etc. should be burned or rinsed in water before putting into refuse bins.

## **Painting instructions**

### **Painting new surfaces**

Let new zinc coated sheet metal roofs oxidize for at least 2 years before painting. Prime with anti-rust primer following the instructions of the manufacturer. Paint the undercoat thinly with Uula Graphite Paint that has been thinned 20–30%. Let dry for approx. 5 days. Finish the surface with un-thinned Uula Graphite Paint.

### **Maintenance painting**

Remove peeling and flaking paint or rust with wirebrush or scraper. Wash the surface with Uula Washing Agent and let dry. Prime rusty and bare patches of the surface with anti-rust primer. Paint the undercoat thinly with Uula Graphite Paint that has been thinned 20– 30%. Let dry for approx. 5 days. Finish the surface with unthinned Uula Graphite Paint.

### **Points to note**

- \*Despite the relatively long drying time Uula Graphite Paint withstands rain immediately after painting.
- \*Stir well before use and during painting
- \*Never paint with Uula Graphite Paint without using anti-rust primer since graphite increases the risk of rusting
- \*In case of uncertainty, submit to the manufacturer of the paint or to a competent distributor before starting the painting process.

Information in the technical specification is based on tests and practical experience. All instructions are only indicative and depend, for example, on the texture of the surface, quality, colour and previous treatments. Because we cannot control the use and working conditions of our products we take responsibility only for the quality of the product and guarantee that it is in accordance with the high standards of Uulatuote Oy. We do not take responsibility for damage caused by using the product against our instructions or intended use.